

Bridgeboro Historic District  
Thomas Haines House  
12 South Bridgeboro Street  
Bridgeboro  
Burlington County  
New Jersey

HABS No. NJ-899-1

HABS  
NJ,  
3-BRIBO,  
1/1-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY  
MID-ATLANTIC REGION NATIONAL PARK SERVICE  
DEPARTMENT OF THE INTERIOR  
PHILADELPHIA, PENNSYLVANIA 19106

HABS  
NJ,  
3.8.81.80,  
1/1-

ARCHITECTURAL DATA FORM

<b>STATE</b> New Jersey		<b>COUNTY</b> Burlington		<b>TOWN OR VICINITY</b> Bridgeboro	
<b>HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)</b> Bridgeboro Historic District				<b>HABS NO.</b> NJ-899-1	
<b>SECONDARY OR COMMON NAMES OF STRUCTURE</b> Thomas Haines House					
<b>COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)</b> 12 South Bridgeboro Street					
<b>DATE OF CONSTRUCTION (INCLUDE SOURCE)</b> Before 1876 (Scott Atlas, 1876)			<b>ARCHITECT(S) (INCLUDE SOURCE)</b> Unknown		
<b>SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)</b> Part of the Bridgeboro Historic District, the most cohesive concentration of nineteenth century buildings in Bridgeboro.					
<b>STYLE (IF APPROPRIATE)</b> Vernacular with Victorian decorative features					
<b>MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)</b> Wood frame					
<b>SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)</b> Rectangular, 21' x 37'. An 8'x8' one-story shed is attached to rear.					
<b>EXTERIOR FEATURES OF NOTE</b> Gable is decorated with fishscale shingles and a round-arched gable window in attic. Side proche with turned columns.					
<b>INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)</b> Three-room deep plan with 2 bay side hall front entrance. Living room (front), dining room (middle), kitchen (rear) compose first floor. Second floor consists of three bedrooms with small bath at top of staircase.					
<b>MAJOR ALTERATIONS AND ADDITIONS WITH DATES</b> Rear one-story frame 8'x8' shed attached to rear of building in early twentieth century.					
<b>PRESENT CONDITION AND USE</b> Building vacated on 1/12/81 and presently in dilapidated condition.					
<b>OTHER INFORMATION AS APPROPRIATE</b>					
<b>SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)</b> Cultural Resource Survey for Rt. 130, 9F, 2/80, by Historic Sites Research. Real estate appraisal 11/2/79 and interior inspection by compiler on 8/23/82. Determination of eligibility on 6/26/81.					
<b>COMPILER, AFFILIATION</b> Dennis DeGregroy, N.J. Department of Transportation					<b>DATE</b> 9/30/82